SCRATCH AND DENT APPRAISAL

APP # Y00276

LOCATION	WRMG #85 FLI	IPPIN, AR	72634	9 14 23 AS IS COMPLETE
BOAT MAKE		Model		HIN
BACKGROUND INFORMATION				
GENERAL CONDITION HULL UPHOLSTERY/SEATS GRAPHICS PAINT DECKS WINDSHIELD STEERING/ELEC TROLLING MOTOR ACCESSORIES MOTOR MAKE	GOOD	FAIR	POOR	Model 2 SER 1
BACKGROUND INFORMATION				
GENERAL CONDITION PAINT PROP POWER TRIM LOWER UNIT HOURS	GOOD	FAIR	POOR D B B B B B B B B B B B B	COMMENTS NO Property of the second
TRAILER MAKE EZ LOADER MODEL Z518 VIN 1L83L5MB4PA000163 BACKGROUND NEW NON CURRENT-2023 INFORMATION				
GENERAL CONDITION PAINT TIRES LIGHTS BRAKES WINCH STAND BUNKS	MISS	SING TOF	P FENDER N	COMMENTS MISSING SPARE ION COMMENTS: HON SKID ON BOTH SIDES
MISSING FRONT FENDER NON SKID ON PORT SIDE INCLUDED WITH BOAT:				