

SCRATCH AND DENT APPRAISAL

APP #
L9184

LOCATION LEBANON

11 / 1 / 2023

AS IS

COMPLETE

BOAT MAKE RANGER Model RB190 HIN RGR51816J324

BACKGROUND INFORMATION NEW BOAT DENT IN BOTTOM
SEE INSPECTION LIST:DENT IN BOTTOM,FLOOR DIRTY,S/S SEAT RUBS BULKHEAD
RIG KIT: 340693

| GENERAL CONDITION | GOOD | FAIR | POOR | COMMENTS |
|-------------------|-------------------------------------|-------------------------------------|--------------------------|------------------------|
| HULL | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | SEE INSPECTION LIST |
| UPHOLSTERY/SEATS | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | DENT IN BOTTOM |
| GRAPHICS | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | FLOOR DIRTY |
| PAINT | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | S/S SEAT RUBS BULKHEAD |
| DECKS | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| WINDSHIELD | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| STEERING/ELEC | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| TROLLING MOTOR | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| ACCESSORIES | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |

MOTOR MAKE MERCURY Model 1 115ELPT Model 2 _____ SER 1 3B490303

BACKGROUND INFORMATION NEW MOTOR

| GENERAL CONDITION | GOOD | FAIR | POOR | COMMENTS |
|-------------------|-------------------------------------|--------------------------|--------------------------|-----------|
| PAINT | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | NEW MOTOR |
| PROP | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| POWER TRIM | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| LOWER UNIT | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | NO ▼ |
| MTR HRS : 0 | WINTERIZED? | | | |

TRAILER MAKE _____ MODEL 371508 VIN 1L83LENA8RA001549

BACKGROUND INFORMATION NEW TRAILER

| GENERAL CONDITION | GOOD | FAIR | POOR | COMMENTS |
|-------------------|-------------------------------------|--------------------------|--------------------------|-------------|
| PAINT | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | NEW TRAILER |
| TIRES | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| LIGHTS | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| BRAKES | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| WINCH STAND | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| BUNKS | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |