## SCRATCH AND DENT APPRAISAL

APP # L9185

LOCATION	DCATION LEBANON						/	1 /	,	2023	AS	i IS	<u> </u>
											СОМ	IPLETE	≣ 🗆
BOAT MAKE	RANGER	Model	2500	HIN	N RGR11208L223								
BACKGROUND	RETURN	BOAT											
INFORMATION			I I IST:FIIFI	S/S P	SOWE,	YF [	)ΔΜΔ(	GED	LOGS	\// ATF	-R ΜΔ	RKS	
in Gravitation	SEE INSPECTION LIST:FUEL IN TANK,S/S BOWEYE DAMAGED,LOGS WATER MARK RIG KIT: 329790												
GENERAL CONDITION	GOOD	FAIR	POOR				(	COMM	IENT	S			
HULL		\				SI	EE II	NSPE	CTIO	N LIST	•		
UPHOLSTERY/SEATS	<b>V</b>			FUEL IN	I TANI	K							
GRAPHICS	7			S/S BOW EYE DAMAGED									
PAINT	<b>\rightarrow</b>			LOGS WATER MARKS									
DECKS	\ \			FURNITURE DIRTY									
WINDSHIELD	7			RUBRAIL DAMAGE UNDER SIDE GATE									
STEERING/ELEC	\\												
TROLLING MOTOR	<b>✓</b>												
ACCESSORIES	<b>V</b>												
MOTOR MAKE	MERCURY	Model 1	300L	Model 2		SER 1	3B	39603	4				
BACKGROUND	MOTOR E	BEEN RA	N 32.3 HOU	JRS									
INFORMATION													
GENERAL CONDITION	GOOD	FAIR	POOR				(	COMM	1ENT	S			
PAINT	7			MOTOR	BEEN	N RAN							
PROP													
POWER TRIM	7												
LOWER UNIT			T T	NO 🔻									
MTR HRS : 32.3	WINTERIZED?												
TDAIL ED MAKE		MODEL				\//							
TRAILER MAKE	<u> </u>	MODEL				- VI	N						
BACKGROUND	No TRAIL	ER											
INFORMATION													
GENERAL CONDITIO	N GOOD	FAIR	POOR				(	COMM	IENT	S			
PAINT				No TRA	II FR			JOIVIIV					
TIRES				.10 1101									
LIGHTS				1									
BRAKES				1									
WINCH STAND													
BUNKS				1									